


五常國中飲水設備維護記錄位置表

巡檢保養 濾芯更換

114 年 10 月 1 日

| 編號 | 安裝位置 |    |         | 廠牌 | 型號         | 電壓   | 年份      | 機號     | 濾芯規格      |     | 機台<br>巡檢 | 漏電<br>檢測 | 加熱<br>系統 | 冷卻<br>系統 | 功能<br>操作 | 備註 |
|----|------|----|---------|----|------------|------|---------|--------|-----------|-----|----------|----------|----------|----------|----------|----|
|    | 樓名   | 樓層 | 位置      |    |            |      |         |        | 第一道       | 第二道 |          |          |          |          |          |    |
| 1  |      | 1F | 游泳池(1樓) | 賀眾 | UW-10000A  | 110v | 2018.12 | 071352 | UF-61.64  |     |          | ✓        | ✓        | ✓        | ✓        |    |
| 2  |      | 2F | 游泳池(2樓) | 賀眾 | UW-10000A  | 110v | 2017.1  | 021185 | UF-61.64  |     |          | ✓        | ✓        | ✓        | ✓        |    |
| 3  |      | 3F | 游泳池(3樓) | 賀眾 | UW-10000A  | 110v | 2018.12 | 071351 | UF-61.64  |     |          | ✓        | ✓        | ✓        | ✓        |    |
| 4  |      | 4F | 游泳池(4樓) | 賀眾 | UW-80000AD | 110v | 2025.01 | 460542 | UF-65.CTO |     |          | ✓        | ✓        | ✓        | ✓        |    |
| 5  |      | 5F | 游泳池(5樓) | 賀眾 | UW-10000A  | 110v | 2017.10 | 021186 | UF-61.64  |     |          | ✓        | ✓        | ✓        | ✓        |    |
| 6  |      | 1F | 後棟1樓女廁旁 | 賀眾 | UW-193     | 110v | 2013.1  | 801872 | UF-65.CTO |     |          | ✓        | ✓        | ✓        | ✓        |    |
| 7  |      | 3F | 活動中心    | 賀眾 | UW-10000A  | 110v | 2018.12 | 071353 | UF-61.64  |     |          | ✓        | ✓        | ✓        | ✓        |    |
| 8  |      | 3F | 後棟3樓女廁旁 | 賀眾 | UW-10000A  | 110v | 2018.12 | 071354 | UF-61.64  |     |          | ✓        | ✓        | ✓        | ✓        |    |
| 9  |      | 1F | 健康中心    | 賀眾 | UW-9615    | 110V | 2022.12 | 334098 | UF-65.CTO |     |          | ✓        | ✓        | ✓        | ✓        |    |
| 10 |      |    |         |    |            |      |         |        |           |     |          |          |          |          |          |    |
| 11 |      |    |         |    |            |      |         |        |           |     |          |          |          |          |          |    |
| 12 |      |    |         |    |            |      |         |        |           |     |          |          |          |          |          |    |
| 13 |      |    |         |    |            |      |         |        |           |     |          |          |          |          |          |    |
| 14 |      |    |         |    |            |      |         |        |           |     |          |          |          |          |          |    |
| 15 |      |    |         |    |            |      |         |        |           |     |          |          |          |          |          |    |
| 16 |      |    |         |    |            |      |         |        |           |     |          |          |          |          |          |    |
| 17 |      |    |         |    |            |      |         |        |           |     |          |          |          |          |          |    |
| 18 |      |    |         |    |            |      |         |        |           |     |          |          |          |          |          |    |
| 19 |      |    |         |    |            |      |         |        |           |     |          |          |          |          |          |    |
| 20 |      |    |         |    |            |      |         |        |           |     |          |          |          |          |          |    |
| 21 |      |    |         |    |            |      |         |        |           |     |          |          |          |          |          |    |

濾芯更換支數: \_\_\_\_\_ 支 巡檢台數: 9 台



服務人員簽章:

承辦人員簽核:

柯偉聖